



FPRN News

February 22, 2017

Network Outage

On February 23, 2017 the FPRN may experience a brief network outage. The network infrastructure is undergoing a change and may cause outages.

Please Plan Accordingly

Network Upgrades

We are in the process of upgrading approximately one half of the FPRN's GNSS receivers. The new receivers will increase network stability and reliability.

New Products

Data Sheets

We now offer Data sheets for each of the FPRN Reference Stations.

<http://www.fdot.gov/geospatial/FPRNDatasheets.shtm>

Virtual Rinex

The Virtual Rinex option is now available.

Network Solutions

When using port 10000 to receive corrections you **must** turn on your NMEA (GGA) message string, and it must be set to broadcast at a rate of less than 30 seconds.

Rinex Service

We are experiencing problems with the file availability page on the FPRN website. Most of the files are available but are not being shown correctly on the web site. If you are in need of a specific file go ahead and make the request. If the system does not respond within 24 hours, send an email requesting the information needed.